

PREVENTIVE RECALL NOTICE

Singing Rock is notifying customers that some of the produced climbing harnesses CRUX, NARA, NEMO may pose a potential casualty hazard due to inaccuracy in the production. This defect was identified at regular internal quality inspection and up to know there are no reports of this defect coming from normal use.

If you own any of mentioned products, please, read this important notice.

Identification - Name of Product/production lots involved:

The lot number can be found on the label as pictured below and is either the 7 digits in the larger lot number. Compare these 7 digits with the list of numbers given below. In the case of a match, return the product to your dealer as directed below.



---/XXXXXX-/--/--
CRUX
SIZE: --

---/XXXXXX-/--/--
NARA
SIZE: --

---/XXXXXX-/--/--
NEMO
SIZE: --

CRUX

1071050; 1071051; 1071130; 1075163; 1075162; 1077978;
1077980; 1062912; 1064334; 1063634; 1071048; 1071049;
1071129; 1075159; 1075160; 1075161; 1080987; 1071046;
1071047; 1071128; 1075158; 1077981; 1086111; 1071054;
1071131; 1077976; 1077977; 1070798; 1071045; 1071127;
1086110

NARA

1071104; 1071105; 1071106; 1075178; 1078062; 1062913;
1063636; 1064362; 1071101; 1071102; 1071103; 1075176;
1075177; 1078063; 1089901; 1086397; 1071093; 1071100;
1075174; 1075175; 1071088; 1071090; 1075173; 1085477;
1085479


NEMO

1071120; 1071121; 1071122; 1075166; 1075167; 1075168;
1089748; 1075169; 1062916; 1064364; 1063638; 1071123;
1071124; 1075170; 1071125; 1075171; 1075172; 1080254;
1086109

Manufacturer: LANEX a.s., division Singing Rock

Date of Manufacture: 10/2010 – 5/2011

Hazard: Possible inaccuracy in production resulting in lower waist belt strength of the harness – see a picture



Till nowadays there are no reports of this defect coming from normal use. Nonetheless, Singing Rock is acting pro-actively on this matter given the potential casualty hazard.

Based on this matter is decided to change construction of stitching for CRUX and construction change of NARA and NEMO to avoid possible safety hazard.

PLEASE RETURN THESE HARNESSSES FOR REPLACEMENT WITH A PERFECT PRODUCT.

Czech Returns:

LANEX a.s., division Singing Rock
Poniklá 317
512 42 Poniklá

Other countries returns:

See-<http://www.singingrock.com/article.asp?nArticleID=1468&nDepartmentID=884&nLanguageID=2>

Thank you for your continued support. Please accept our sincere apologies for any inconvenience this may cause you.